Tribally-driven usage of Road Safety Audit (RSA) to prevent motor vehicle crashes

American Public Health Association Conference November 19, 2014

Presenters: Kim Townsend and Janey Bryan


Learning Objectives

- Discover how a Road Safety Audit (RSA) is conducted and the role of injury prevention and public health professionals in the process
- Understand how a RSA applies evidence based practices to reduce motor vehicle crashes
- Learn how to utilize a RSA to identify hazards and target environmental interventions

Background


- Duckwater Shoshone Reservation (3,854 acres) is located in central Nevada
- Population on the reservation is n=151
- Essential services are1-2 hours away
- Tribal injury prevention coalition initiated RSA with Nevada Department of Transportation (NDOT)

Service Destination Near Duckwater Shoshone Reservation



Duckwater RSA Process


8-Step Road Safety Audit



Step 1: Identify Roads

Compiled 12 years of crash data to identify crash locations prior to RSA field review:

- NDOT crash data from law enforcement agencies
- Duckwater police crash reports



Step 1: Identify Roads

- ▶ Total crashes, 2002-2013: n=20
- Severity:
 - ▶ Fatal crashes: 5
 - Injury crashes: 3
 - Property damage crashes: 12
- Crash Factors:
 - Crashes in clear weather: 14
 - Crashes in low light conditions: 11
 - Crashes where vehicle left the roadway: 10
 - Crashes involving animals: 7

Step 2: Identify RSA Team

NDOT contracted Kimley Horn and Associates, Inc. to conduct the RSA with team:



- Duckwater Police
- Duckwater Planning
- Inter Tribal Council of Arizona, Inc.
 - Transportation/Injury Prevention
 - Engineering Consultant
- NDOT District Engineering
- Nye County Road Maintenance

Step 3: Start-up Meeting

- ► Injury prevention coalition relayed to RSA team the safety concerns on existing routes owned by Duckwater, Bureau of Indian Affairs (BIA) and State 379
 - ▶ 17 miles unimproved section of route 379
 - Wild and domestic animals in roadway
 - Flooding/road erosion







Step 4: Perform Field Review – Duckwater/BIA Routes

Tribal and BIA-owned roads within Duckwater. Issues:

- Pavement markers
- Signage
- Culverts/drainage
- Street lighting
- Pedestrian crossing
- Cattle guards







Step 4: Perform Field Review – State Route 379

NDOT-owned road provides access to services. Two counties maintain route 379.



Issues:

- Road condition
 - Large, sharp aggregate (gravel)
 - Dust control
 - Deteriorating pavement edge
- Drainage/culverts
- Pavement markers
- Signage
- Fencing





Step 5: Prepare Findings

RSA Team

- After the field reviews, discussed the findings
 - Findings log
 - Pictures
- Suggested engineering and behavioral evidence-based strategies





Step 6: Present Findings

Kimley Horn and Associates, Inc.

- Summarized the findings for the injury prevention coalition the day after the RSA
- Drafted RSA report for tribal review
- Provided tribe RSA report for injury prevention and transportation safety planning







Step 7: Prepare Formal Response

Jurisdictions of road ownership are required to formally respond to the RSA

- Duckwater coalition reviewed the RSA report and recommendations
- Duckwater Tribal Council approved the letter accepting the RSA findings

Step 8: Incorporate Findings into Projects

Duckwater police: injury prevention coalition

- Crash surveillance
- Occupant protection promotion
- Assessments
 - Observational seatbelt surveys
 - Distracted driving assessment
- Speed enforcement
- Traffic code review

Duckwater planning: transportation

- Applied for safety project funds to address the pedestrian crossing near the school and clinic
- Updating the Long Range Transportation Plan safety chapter
- Addressing safety funding match for Tribal and BIA road project improvements

Acknowledgements

Motor Vehicle Injury Prevention Coalition

- ▶ **Funding**: Office of Minority Health, Department of Health and Human Services
- ▶ **Technical Assistance**: Inter Tribal Council of Arizona, Inc., Tribal Epidemiology Center

RSA

- Funding: NDOT, Safety Engineering
- ► **Technical Assistance**: Kimley Horn and Associates, Inc.